

Muge K Akin

List of Publications by Year in descending order

Source: <https://exaly.com/author-pdf/1856005/publications.pdf>

Version: 2024-02-01

21
papers

375
citations

933447

10
h-index

839539

18
g-index

23
all docs

23
docs citations

23
times ranked

346
citing authors

#	ARTICLE	IF	CITATIONS
1	Evaluation of seismic site classification for Kahramanmaras City, Turkey. <i>Environmental Earth Sciences</i> , 2021, 80, 1.	2.7	8
2	Assessment of the effectiveness of a rockfall ditch through 3-D probabilistic rockfall simulations and automated image processing. <i>Engineering Geology</i> , 2021, 283, 106001.	6.3	16
3	VS (30) Tabanlı Yerel Zemin Koşulları ve Deprem Hasar Potansiyeli: Van-Abdurrahmangazi Bölgesi. <i>Jeoloji Mühendisliği Dergisi</i> , 2021, 45, 181-198.	0.1	1
4	A Comparative Study on the VS30 and N30 Based Seismic Site Classification in Kahramanmaras, Turkey. <i>Advances in Civil Engineering</i> , 2020, 2020, 1-15.	0.7	10
5	Rockfall Hazard Assessment Around Ankara Citadel (Turkey) Using Rockfall Analyses and Hazard Rating System. <i>Geotechnical and Geological Engineering</i> , 2020, 38, 3831-3851.	1.7	11
6	A study of the relationship between the pressuremeter modulus and the preconsolidation pressure around a thrust fault. <i>Environmental Earth Sciences</i> , 2019, 78, 1.	2.7	3
7	Impact of Jet-Grouting Pressure on the Strength and Deformation Characteristics of Sandy and Clayey Soils in the Compression Zone. <i>KSCE Journal of Civil Engineering</i> , 2019, 23, 3340-3352.	1.9	11
8	Comparison of SPT and Vs-based liquefaction analyses: a case study in Erciş (Van, Turkey). <i>Acta Geophysica</i> , 2018, 66, 21-38.	2.0	15
9	Landslide Investigation of a Residential Area in Çarşamba Village, Bursa (Turkey). , 2017, , 281-288.		0
10	Experimental studies on the physico-mechanical properties of jet-grout columns in sandy and silty soils. <i>Journal of African Earth Sciences</i> , 2016, 116, 190-197.	2.0	13
11	Dynamic soil characterization and site response estimation for Erbaa, Tokat (Turkey). <i>Natural Hazards</i> , 2016, 82, 1833-1868.	3.4	14
12	Evaluation of liquefaction in Karasu River floodplain after the October 23, 2011, Van (Turkey) earthquake. <i>Natural Hazards</i> , 2013, 69, 1551-1575.	3.4	13
13	A newly developed seismic microzonation model of Erbaa (Tokat, Turkey) located on seismically active eastern segment of the North Anatolian Fault Zone (NAFZ). <i>Natural Hazards</i> , 2013, 65, 1411-1442.	3.4	13
14	Seismic Microzonation of Erbaa, Tokat Province, Turkey, Based on Analytical Hierarchical Process. <i>Environmental and Engineering Geoscience</i> , 2012, 18, 191-207.	0.9	3
15	Rockfall hazard analysis for an historical Castle in Kastamonu (Turkey). <i>Natural Hazards</i> , 2012, 62, 255-274.	3.4	26
16	Empirical correlations of shear wave velocity (Vs) and penetration resistance (SPT-N) for different soils in an earthquake-prone area (Erbaa-Turkey). <i>Engineering Geology</i> , 2011, 119, 1-17.	6.3	87
17	Investigation of the Macro Pore Geometry of Yellow Travertines Using the Shape Parameter Approach. <i>Environmental and Engineering Geoscience</i> , 2009, 15, 197-209.	0.9	4
18	Geotechnical assessment of a landslide along a natural gas pipeline for possible remediations (Karacabey-Turkey). <i>Environmental Geology</i> , 2009, 57, 611.	1.2	16

#	ARTICLE	IF	CITATIONS
19	Assessment of rockfall hazard around Afyon Castle, Turkey. Environmental Geology, 2007, 53, 191-200.	1.2	60
20	Seismic hazard map of Turkey using the deterministic approach. Engineering Geology, 2003, 69, 127-137.	6.3	39
21	Mikrobölgeleme Açılmasıyla Altıncı Oluşturmak Üzere Van Yüzölçümü Kampüsü Zemininin Dinamik Özelliklerinin Belirlenmesi. Jeoloji Mühendisliği Dergisi, 0, , 1-1.	0.1	6