

# Å°smail DÄ°nÄer

## List of Publications by Year in descending order

Source: <https://exaly.com/author-pdf/2267310/publications.pdf>

Version: 2024-02-01

17  
papers

353  
citations

933447

10  
h-index

1058476

14  
g-index

17  
all docs

17  
docs citations

17  
times ranked

339  
citing authors

#	ARTICLE	IF	CITATIONS
1	Correlation between Schmidt hardness, uniaxial compressive strength and Young's modulus for andesites, basalts and tuffs. <i>Bulletin of Engineering Geology and the Environment</i> , 2004, 63, 141-148.	3.5	128
2	Estimation of strength and deformation properties of Quaternary caliche deposits. <i>Bulletin of Engineering Geology and the Environment</i> , 2008, 67, 353-366.	3.5	41
3	The effects of discontinuity surface roughness on the shear strength of weathered granite joints. <i>Bulletin of Engineering Geology and the Environment</i> , 2014, 73, 801-813.	3.5	33
4	Experimental studies on ignimbrite and the effect of lichens and capillarity on the deterioration of Seljuk Gravestones. <i>Engineering Geology</i> , 2015, 185, 81-95.	6.3	33
5	Models to predict the deformation modulus and the coefficient of subgrade reaction for earth filling structures. <i>Advances in Engineering Software</i> , 2011, 42, 160-171.	3.8	20
6	Capillary water absorption characteristics of some Cappadocian ignimbrites and the role of capillarity on their deterioration. <i>Environmental Earth Sciences</i> , 2019, 78, 1.	2.7	19
7	Assessment of the effectiveness of a rockfall ditch through 3-D probabilistic rockfall simulations and automated image processing. <i>Engineering Geology</i> , 2021, 283, 106001.	6.3	16
8	Rockfall at the heritage site of the Tatlarin Underground City (Cappadocia, Turkey). <i>Natural Hazards</i> , 2016, 82, 1075-1098.	3.4	15
9	Evaluation of the physico-mechanical parameters affecting the deterioration rate of Ahlat ignimbrites (Bitlis, Turkey). <i>Environmental Earth Sciences</i> , 2017, 76, 1.	2.7	14
10	Core size and time effects on water absorption values of rock and cement mortar samples. <i>Bulletin of Engineering Geology and the Environment</i> , 2009, 68, 483-489.	3.5	13
11	Quality Assessment of Geo-Materials for Coastal Structures (Yumurtalık, Turkey). <i>Marine Georesources and Geotechnology</i> , 2011, 29, 299-316.	2.1	9
12	Left upstream slope design for the Atatürk Dam, Adana, Turkey and its behaviour under actual earthquake loading. <i>Engineering Geology</i> , 2005, 82, 1-11.	6.3	4
13	Geotechnical characteristics of the clayey soils and rocks of the North Lefkoşa, Nicosia, Cyprus. <i>Bulletin of Engineering Geology and the Environment</i> , 2007, 66, 473-481.	3.5	3
14	Engineering properties and dynamic behavior of caliche deposits in a seismically active region in southern Turkey. <i>Engineering Geology</i> , 2010, 111, 73-89.	6.3	2
15	Nevşehir Pomza Endüstrisinin Genel Değerlendirilmesi. <i>Nevşehir Bilim Ve Teknoloji Dergisi</i> , 2017, 6, 571-579.		2
16	Rock Mass Instabilities in Tatlarin Underground City (Cappadocia-Turkey)., 2015, , 361-365.		1
17	Reply to discussion by Alavi and Gandomi on "Models to predict the deformation modulus and the coefficient of subgrade reaction for earth filling structures" by Ismail Dinışer [Adv. Eng. Software 42 (2011) 160-171]. <i>Advances in Engineering Software</i> , 2013, 56, 15-22.	3.8	0