

Damage assessment of churches after L'Aquila earthquake

Bulletin of Earthquake Engineering

10, 73-92

DOI: [10.1007/s10518-011-9307-x](https://doi.org/10.1007/s10518-011-9307-x)

Citation Report

#	ARTICLE	IF	CITATIONS
1	Field observations and interpretation of the structural performance of constructions after the 11 May 2011 Lorca earthquake. <i>Engineering Failure Analysis</i> , 2013, 34, 670-692.	1.8	114
2	Damage and performance evaluation of masonry churches in the 2009 L'Aquila earthquake. <i>Engineering Failure Analysis</i> , 2013, 34, 693-714.	1.8	189
3	Statistical Assessment of Damage to Churches Affected by the 2010-2011 Canterbury (New Zealand) Earthquake Sequence. <i>Journal of Earthquake Engineering</i> , 2013, 17, 73-97.	1.4	47
4	The Effect of Stiffened Floor and Roof Diaphragms on the Experimental Seismic Response of a Full-Scale Unreinforced Stone Masonry Building. <i>Journal of Earthquake Engineering</i> , 2014, 18, 407-443.	1.4	79
5	Observations of Out-of-Plane Rocking in the Oratory of San Giuseppe Dei Minimi during the 2009 L'Aquila Earthquake. <i>Applied Mechanics and Materials</i> , 0, 621, 101-106.	0.2	21
6	The behaviour of vernacular buildings in the 2012 Emilia earthquakes. <i>Bulletin of Earthquake Engineering</i> , 2014, 12, 2367-2382.	2.3	48
7	Evaluation of Seismic Vulnerability of Santa Maria del Mar in Barcelona by an Integrated Approach Based on Terrestrial Laser Scanner and Finite Element Modeling. <i>International Journal of Architectural Heritage</i> , 2014, 8, 795-819.	1.7	27
8	Damage assessment of fortresses after the 2012 Emilia earthquake (Italy). <i>Bulletin of Earthquake Engineering</i> , 2014, 12, 2333-2365.	2.3	80
9	In-plane stiffening techniques with nail plates or CFRP strips for timber floors in historical masonry buildings. <i>Construction and Building Materials</i> , 2014, 58, 64-76.	3.2	46
10	The effects of L'Aquila earthquake on the St. Gemma church in Goriano Sicoli: part I damage survey and kinematic analysis. <i>Bulletin of Earthquake Engineering</i> , 2015, 13, 3713-3732.	2.3	27
11	An integrated survey experience for assessing the seismic vulnerability of Senigallia's Fortress (Italy): documentation for conservation and FEM modeling. , 2015, , .		4
12	The dynamic behaviour of the roof interventions in the Basilica San Francesco in Assisi. , 2015, , .		0
13	The relative dynamic resilience of masonry collapse mechanisms. <i>Engineering Structures</i> , 2015, 85, 182-194.	2.6	29
14	Damage Assessment of Unreinforced Stone Masonry Buildings After the 2010-2011 Canterbury Earthquakes. <i>International Journal of Architectural Heritage</i> , 2015, 9, 605-627.	1.7	20
15	Closed form solution for predicting the horizontal capacity of masonry portal frames through limit analysis and comparison with experimental test results. <i>Engineering Failure Analysis</i> , 2015, 55, 246-270.	1.8	22
16	Comparison of seismic analysis methods applied to a historical church struck by 2009 L'Aquila earthquake. <i>Bulletin of Earthquake Engineering</i> , 2015, 13, 3749-3778.	2.3	41
17	Seismic Performance of Historical Masonry Structures Through Pushover and Nonlinear Dynamic Analyses. <i>Geotechnical, Geological and Earthquake Engineering</i> , 2015, , 265-292.	0.1	38
18	PERPETUATE guidelines for seismic performance-based assessment of cultural heritage masonry structures. <i>Bulletin of Earthquake Engineering</i> , 2015, 13, 13-47.	2.3	198

#	ARTICLE	IF	CITATIONS
19	Seismic performance of masonry walls retrofitted with steel reinforced grout. <i>Earthquake Engineering and Structural Dynamics</i> , 2016, 45, 229-251.	2.5	42
20	The Dynamic Behavior of the Basilica of San Francesco in Assisi Using Simplified Analytical Models. <i>International Journal of Architectural Heritage</i> , 2016, 10, 938-953.	1.7	8
21	Observed and predicted earthquake damage scenarios: the case study of Pettino (L'Aquila) after the 6th April 2009 event. <i>Bulletin of Earthquake Engineering</i> , 2016, 14, 2643-2678.	2.3	27
22	ANTAEUS Project for the Regional Vulnerability Assessment of the Current Building Stock in Historical Centers. <i>International Journal of Architectural Heritage</i> , 2016, 10, 20-43.	1.7	41
23	Masonry walls with irregular texture of L'Aquila (Italy) seismic area: validation of a method for the evaluation of masonry quality. <i>Materials and Structures/Materiaux Et Constructions</i> , 2016, 49, 2297-2314.	1.3	35
24	Seismic safety assessment of historical structures using updated numerical models: The case of Mallorca cathedral in Spain. <i>Engineering Failure Analysis</i> , 2017, 74, 54-79.	1.8	27
25	A 3D microstructured cohesive-frictional interface model and its rational calibration for the analysis of masonry panels. <i>International Journal of Solids and Structures</i> , 2017, 122-123, 110-127.	1.3	21
26	Structural Characterization and Seismic Performance of San Francisco Church, the Most Ancient Monument in Santiago, Chile. <i>International Journal of Architectural Heritage</i> , 0, , 1-25.	1.7	6
27	Damage assessment of three medieval churches after the 2012 Emilia earthquake. <i>Bulletin of Earthquake Engineering</i> , 2017, 15, 2939-2980.	2.3	36
28	A numerical procedure for the pushover analysis of masonry towers. <i>Soil Dynamics and Earthquake Engineering</i> , 2017, 93, 162-171.	1.9	20
29	Seismic vulnerability evaluation of historical masonry churches: Proposal for a general and comprehensive numerical approach to cross-check results. <i>Engineering Failure Analysis</i> , 2017, 82, 208-228.	1.8	24
30	Experimental cyclic and dynamic in-plane rocking response of a masonry transverse arch typical of historical churches. <i>Engineering Structures</i> , 2017, 147, 285-296.	2.6	4
31	Horizontally restrained rocking blocks: evaluation of the role of boundary conditions with static and dynamic approaches. <i>Bulletin of Earthquake Engineering</i> , 2017, 15, 385-410.	2.3	44
32	Vulnerability Assessment of Unreinforced Masonry Churches Following the 2010-2011 Canterbury Earthquake Sequence. <i>Journal of Earthquake Engineering</i> , 2017, 21, 912-934.	1.4	28
33	An insight in the late Baroque architecture: An integrated approach for a unique Bibiena church. <i>Journal of Cultural Heritage</i> , 2017, 23, 58-67.	1.5	30
34	Multi-Directional Seismic Assessment of Historical Masonry Buildings by Means of Macro-Element Modelling: Application to a Building Damaged during the L'Aquila Earthquake (Italy). <i>Buildings</i> , 2017, 7, 106.	1.4	18
35	Assessment of risks on a territorial scale for archaeological sites in Åzmir. <i>International Journal of Architectural Heritage</i> , 2018, 12, 951-980.	1.7	11
36	UB-ALMANAC: An adaptive limit analysis NURBS-based program for the automatic assessment of partial failure mechanisms in masonry churches. <i>Engineering Failure Analysis</i> , 2018, 85, 201-220.	1.8	50

#	ARTICLE	IF	CITATIONS
37	Seismic response and damage patterns of masonry churches: Seven case studies in Ferrara, Italy. <i>Engineering Structures</i> , 2018, 177, 809-835.	2.6	44
38	Damage assessment and partial failure mechanisms activation of historical masonry churches under seismic actions: Three case studies in Mantua. <i>Engineering Failure Analysis</i> , 2018, 92, 495-519.	1.8	58
39	The effects of in-plane shear displacements at the springings of Gothic cross vaults. <i>Construction and Building Materials</i> , 2018, 186, 219-232.	3.2	20
40	Reducing the Loss of Built Heritage in Seismic Areas. <i>Buildings</i> , 2018, 8, 19.	1.4	11
41	Assessment of Post-Earthquake Damage: St. Salvatore Church in Acquapagana, Central Italy. <i>Buildings</i> , 2018, 8, 45.	1.4	6
42	Seismic vulnerability scenarios of Unreinforced Masonry churches in New Zealand. <i>Bulletin of Earthquake Engineering</i> , 2018, 16, 3957-3999.	2.3	10
43	Evaluation of Seismic Risk on UNESCO Cultural Heritage sites in Europe. <i>International Journal of Architectural Heritage</i> , 2018, 12, 1231-1244.	1.7	24
44	Seismic damage survey and empirical fragility curves for churches after the August 24, 2016 Central Italy earthquake. <i>Soil Dynamics and Earthquake Engineering</i> , 2018, 111, 98-109.	1.9	51
45	Numerical Simulation and Failure Analysis of St. Konstantinos Church, after the Kozani Earthquake. <i>International Journal of Civil Engineering</i> , 2019, 17, 949-967.	0.9	4
46	Integrated approach for seismic vulnerability analysis of historic massive defensive structures. <i>Journal of Cultural Heritage</i> , 2019, 35, 86-98.	1.5	31
47	Damage survey, simplified assessment, and advanced seismic analyses of two masonry churches after the 2012 Emilia earthquake. <i>International Journal of Architectural Heritage</i> , 2019, 13, 901-924.	1.7	39
48	Hybrid seismic base isolation of a historical masonry church using unbonded fiber reinforced elastomeric isolators and shape memory alloy wires. <i>Engineering Structures</i> , 2019, 196, 109281.	2.6	41
49	Comparative Seismic Assessment Methods for Masonry Building Aggregates: A Case Study. <i>Frontiers in Built Environment</i> , 2019, 5, .	1.2	27
50	Post-Earthquake Damage and Vulnerability Assessment of Churches in the Marche Region Struck by the 2016 Central Italy Seismic Sequence. <i>International Journal of Architectural Heritage</i> , 2021, 15, 1000-1021.	1.7	28
51	Evaluation of the Performance of Unreinforced Stone Masonry Greek "Basilica" Churches When Subjected to Seismic Forces and Foundation Settlement. <i>Buildings</i> , 2019, 9, 106.	1.4	3
52	Performance-based assessment of masonry churches: application to San Clemente Abbey in Castiglione a Casauria (Italy). , 2019, , 55-89.		0
53	Seismic assessment of historical masonry structures through advanced nonlinear dynamic simulations: applications to castles, churches, and palaces. , 2019, , 163-200.		4
54	Seismic Vulnerability Analysis and Retrofitting of the SS. Rosario Church Bell Tower in Finale Emilia (Modena, Italy). <i>Frontiers in Built Environment</i> , 2019, 5, .	1.2	12

#	ARTICLE	IF	CITATIONS
55	Predictive model for seismic vulnerability assessment of churches based on the 2009 L'Aquila earthquake. <i>Bulletin of Earthquake Engineering</i> , 2019, 17, 4909-4936.	2.3	41
56	Advanced numerical insights into failure analysis and strengthening of monumental masonry churches under seismic actions. <i>Engineering Failure Analysis</i> , 2019, 103, 410-430.	1.8	50
57	Comparative Seismic Assessment of Ancient Masonry Churches. <i>Frontiers in Built Environment</i> , 2019, 5, .	1.2	21
58	Damage to churches in the 2016 central Italy earthquakes. <i>Bulletin of Earthquake Engineering</i> , 2019, 17, 5763-5790.	2.3	71
59	Earthquake damage assessment of masonry churches: proposal for rapid and detailed forms and derivation of empirical vulnerability curves. <i>Bulletin of Earthquake Engineering</i> , 2019, 17, 3327-3364.	2.3	21
60	Performance of a Far-Field Historical Church during the 2016-2017 Central Italy Earthquakes. <i>Journal of Performance of Constructed Facilities</i> , 2019, 33, 04019016.	1.0	6
61	Base seismic isolation of a historical masonry church using fiber reinforced elastomeric isolators. <i>Soil Dynamics and Earthquake Engineering</i> , 2019, 120, 127-145.	1.9	43
62	Urban Seismic Networks, Structural Health and Cultural Heritage Monitoring: The National Earthquakes Observatory (INGV, Italy) Experience. <i>Frontiers in Built Environment</i> , 2019, 5, .	1.2	18
63	Influence of geometry on seismic capacity of circular buttressed arches. <i>Journal of Mechanics of Materials and Structures</i> , 2019, 14, 645-661.	0.4	2
64	The 2005 Kashmir Earthquake - devastation of infrastructures. <i>Proceedings of the Institution of Civil Engineers: Structures and Buildings</i> , 2019, 172, 490-501.	0.4	6
65	Window opening effects on structural behavior of historical masonry Fatih Mosque. <i>International Journal of Architectural Heritage</i> , 2019, 13, 585-599.	1.7	9
66	Simplified Seismic Analyses of Ancient Churches in Matera's Landscape. <i>International Journal of Architectural Heritage</i> , 2020, 14, 119-138.	1.7	33
67	Preliminary Assessment on Seismic Vulnerability of Masonry Churches in Central Chile. <i>International Journal of Architectural Heritage</i> , 2020, 14, 829-848.	1.7	17
68	Numerical approaches for cross-laminated timber roof structure optimization in seismic retrofitting of a historical masonry church. <i>Bulletin of Earthquake Engineering</i> , 2020, 18, 487-512.	2.3	20
69	Seismic Vulnerability Assessment and Retrofitting Strategies of Italian Masonry Churches of the Alife-Caiazzo Diocese in Caserta. <i>International Journal of Architectural Heritage</i> , 2020, 14, 1180-1195.	1.7	15
70	Collapse and damage to vernacular buildings induced by 2012 Emilia earthquakes. <i>Bulletin of Earthquake Engineering</i> , 2020, 18, 1049-1080.	2.3	8
71	Experimental test on a fibre-reinforced scaled cross vault subjected to in-plane shear displacements at the springings. <i>Construction and Building Materials</i> , 2020, 265, 120305.	3.2	6
72	The S. Maria di Collemaggio Basilica: From Vulnerability Assessment to First Results of SHM. <i>Journal of Architectural Engineering</i> , 2020, 26, 05020007.	0.8	22

#	ARTICLE	IF	CITATIONS
73	Empirical predictive model for seismic damage of historical churches. <i>Bulletin of Earthquake Engineering</i> , 2020, 18, 6015-6037.	2.3	12
74	Damage Assessment of Historic Masonry Churches Exposed to Slow-moving Landslides. <i>International Journal of Architectural Heritage</i> , 2021, 15, 1170-1195.	1.7	11
75	Seismic Vulnerability Analysis of Masonry Churches in Piemonte after 2003 Valle Scrivia Earthquake: Post-event Screening and Situation 17 Years Later. <i>International Journal of Architectural Heritage</i> , 2022, 16, 717-745.	1.7	39
76	Ground Response and Historical Buildings in Avellino (Campania, Southern Italy): Clues from a Retrospective View Concerning the 1980 Irpinia-Basilicata Earthquake. <i>Geosciences (Switzerland)</i> , 2020, 10, 503.	1.0	2
77	Seismic Vulnerability and Simplified Safety Assessments of Masonry Churches in the Ischia Island (Italy) after the 2017 Earthquake. <i>International Journal of Architectural Heritage</i> , 2022, 16, 136-162.	1.7	20
78	Analytical modelling of out-of-plane flexural response of unreinforced and strengthened masonry walls. <i>Engineering Structures</i> , 2020, 218, 110797.	2.6	9
79	Seismic capacity of buttressed masonry arches. <i>Engineering Structures</i> , 2020, 215, 110661.	2.6	12
80	Correlation of Vulnerability and Damage between Artistic Assets and Structural Elements: The DataBAES Archive for the Conservation Planning of CH Masonry Buildings in Seismic Areas. <i>Sustainability</i> , 2020, 12, 653.	1.6	7
81	Seismic damage and fragility assessment of ancient masonry churches located in central Chile. <i>Bulletin of Earthquake Engineering</i> , 2020, 18, 3433-3457.	2.3	18
82	Traditional T-F Masonries in the City Centre of L'Aquila "The Baraccato Aquilano". <i>International Journal of Architectural Heritage</i> , 2021, 15, 437-454.	1.7	20
83	Seismic response of a masonry church in Central Italy: the role of interventions on the roof. <i>Bulletin of Earthquake Engineering</i> , 2021, 19, 1151-1179.	2.3	19
84	An Indicator for Post-disaster Economic Loss Valuation of Impacts on Cultural Heritage. <i>International Journal of Architectural Heritage</i> , 2021, 15, 678-697.	1.7	18
85	Integration of a Wearable Mobile Mapping Solution and Advance Numerical Simulations for the Structural Analysis of Historical Constructions: A Case of Study in San Pedro Church (Palencia). <i>Journal of Cultural Heritage</i> , 2021, 50, 100-110.	1.0	50
86	Automatic Procedures for the Safety Assessment of Stand-alone Masonry Arches. <i>International Journal of Architectural Heritage</i> , 2022, 16, 1306-1324.	1.7	7
87	Towards the updated Italian seismic risk assessment: exposure and vulnerability modelling. <i>Bulletin of Earthquake Engineering</i> , 2021, 19, 3253-3286.	2.3	48
88	Tuned Mass Damper Design for Slender Masonry Structures: A Framework for Linear and Nonlinear Analysis. <i>Applied Sciences (Switzerland)</i> , 2021, 11, 3425.	1.3	8
89	Damage Assessment of Historical Masonry Churches Subjected to Moderate Intensity Seismic Shaking. <i>Sustainability</i> , 2021, 13, 4710.	1.6	2
90	Experimental and Numerical Assessment of Seismic Retrofit Solutions for Stone Masonry Buildings. <i>Geosciences (Switzerland)</i> , 2021, 11, 230.	1.0	4

#	ARTICLE	IF	CITATIONS
91	Impulsive Signals Produced by Earthquakes in Italy and Their Potential Relation with Site Effects and Structural Damage. <i>Geosciences (Switzerland)</i> , 2021, 11, 261.	1.0	4
92	State of the art of simplified analytical methods for seismic vulnerability assessment of unreinforced masonry buildings. <i>Engineering Structures</i> , 2021, 239, 112280.	2.6	57
93	Integrated framework to structurally model unreinforced masonry Italian medieval churches from photogrammetry to finite element model analysis through heritage building information modeling. <i>Engineering Structures</i> , 2021, 241, 112439.	2.6	14
94	Shaking table testing of groin vaults made by 3D printers. <i>Soil Dynamics and Earthquake Engineering</i> , 2021, 150, 106880.	1.9	7
95	Seismic vulnerability assessment and earthquake response of slender historical masonry bell towers in South-East Lombardia. <i>Engineering Failure Analysis</i> , 2021, 129, 105656.	1.8	45
96	On the collapse of the masonry Medici tower: An integrated discrete-analytical approach. <i>Engineering Structures</i> , 2021, 246, 113046.	2.6	20
97	Seismic risk assessment and intervention prioritization for Italian medieval churches. <i>Journal of Building Engineering</i> , 2021, 43, 103061.	1.6	7
98	Numerical procedures for the analysis of collapse mechanisms of masonry structures using discrete element modelling. <i>Engineering Structures</i> , 2021, 246, 113047.	2.6	21
99	The 2016 Central Italy seismic sequence: linear and non-linear interpretation models for damage evolution in S. Agostino's church in Amatrice. <i>Bulletin of Earthquake Engineering</i> , 2021, 19, 1467-1507.	2.3	5
100	On the Dynamic Performance of the Santa Maria Maddalena Church, Ischia Island (Italy): Numerical and Experimental Comparative Analysis. <i>Lecture Notes in Civil Engineering</i> , 2021, , 699-723.	0.3	2
101	Seismic Upgrading of a Historical Masonry Bell Tower through an Internal Dissipative Steel Structure. <i>Buildings</i> , 2021, 11, 24.	1.4	15
102	Conservation Principles and Performance Based Strengthening of Heritage Buildings in Post-event Reconstruction. <i>Geotechnical, Geological and Earthquake Engineering</i> , 2014, , 489-514.	0.1	12
103	Unidirectional Cyclic Behavior of Old Masonry Walls in Romania. <i>Springer Natural Hazards</i> , 2016, , 351-361.	0.1	4
105	Performance of unreinforced masonry and infilled RC buildings during the 2015 Gorkha, Nepal earthquake sequence. , 2016, , 2399-2408.		9
106	Performance of unreinforced masonry and infilled RC buildings during the 2015 Gorkha, Nepal earthquake sequence. , 2016, , 2399-2407.		3
107	Investigations of masonry churches seismic performance with numerical models: application to a case study. <i>Archives of Civil and Mechanical Engineering</i> , 2021, 21, 1.	1.9	7
108	Structural Design for Large Displacement Demands in Romania. <i>SpringerBriefs in Geotechnical and Earthquake Engineering</i> , 2018, , 41-74.	0.2	0
110	La influencia de las alteraciones estructurales en los daños del terremoto de Amatrice, Italia (2016). <i>Informes De La Construccion</i> , 2020, 72, 349.	0.1	3

#	ARTICLE	IF	CITATIONS
111	Masonry vaulted structures under spreading supports: Analyses of fracturing behavior and size effect. <i>Journal of Building Engineering</i> , 2022, 45, 103396.	1.6	10
112	Calibration of vulnerability and fragility curves from moderate intensity Italian earthquake damage data. <i>International Journal of Disaster Risk Reduction</i> , 2022, 67, 102676.	1.8	11
113	Seismic Vulnerability Assessment for Masonry Churches: An Overview on Existing Methodologies. <i>Buildings</i> , 2021, 11, 588.	1.4	7
114	The Performance of Two Unreinforced Masonry Churches in Greece Under Gravitation and Earthquake Actions. <i>Lecture Notes in Civil Engineering</i> , 2022, , 691-710.	0.3	0
115	Emergency Interventions in the Castle Church of Monreal De Ariza (Spain). <i>Lecture Notes in Civil Engineering</i> , 2022, , 857-869.	0.3	0
116	An Aggregated Non-Destructive Testing (Ndt) Framework for the Assessment of Mechanical Properties of Unreinforced Masonry Italian Medieval Churches. <i>SSRN Electronic Journal</i> , 0, , .	0.4	0
117	Seismic behavior and damage assessment of two historical fortified masonry palaces with corner towers. <i>Engineering Failure Analysis</i> , 2022, 134, 106003.	1.8	42
118	Monitoring Horizontal Movement of Top of a Spire in Saint Mary Cathedral of Burgos via Computer Vision. <i>International Journal of Architectural Heritage</i> , 2023, 17, 1405-1427.	1.7	0
119	Damage to Churches after the 2016 Central Italy Seismic Sequence. <i>Geosciences (Switzerland)</i> , 2022, 12, 122.	1.0	3
120	Selection and spectral matching of recorded ground motions for seismic fragility analyses. <i>Bulletin of Earthquake Engineering</i> , 2022, 20, 4961-4987.	2.3	29
121	Post-Earthquake Damage Assessments of Historic Mosques and Effects of Near-Fault and Far-Fault Ground Motions on Seismic Responses. <i>International Journal of Architectural Heritage</i> , 2023, 17, 1043-1078.	1.7	13
122	Simplified numerical approach for the structural analysis of monumental historical aggregates: the case study of Certosa di Calci. <i>Bulletin of Earthquake Engineering</i> , 2022, 20, 5269-5300.	2.3	4
123	Dynamic characteristics of built heritage using ambient noise recordings. <i>Heritage Science</i> , 2022, 10, .	1.0	0
124	Factors Affecting the Seismic Analysis of Historical Masonry Structures: Case of a Single-Nave Church Damaged during the 2009 L'Aquila Earthquake. <i>Journal of Architectural Engineering</i> , 2022, 28, .	0.8	0
125	Two Steps Procedure for the Finite Elements Seismic Analysis of the Casamari Gothic Church. <i>Buildings</i> , 2022, 12, 1451.	1.4	2
126	A Geotechnical Analysis to Assess the Effect of Slow-Moving Landslides on Historic Masonry Churches. <i>International Journal of Architectural Heritage</i> , 2023, 17, 3-22.	1.7	3
127	Damage assessment in single-nave churches and analysis of the most recurring mechanisms after the 2016-2017 central Italy earthquakes. <i>Bulletin of Earthquake Engineering</i> , 2022, 20, 8031-8059.	2.3	11
128	An integrated approach for the conservation of archaeological buildings: The Re Barbaro Palace in Sardinia. <i>Digital Applications in Archaeology and Cultural Heritage</i> , 2022, 27, e00244.	0.9	0

#	ARTICLE	IF	CITATIONS
129	An expeditious tool for the vulnerability assessment of masonry structures in post-earthquake reconstruction. <i>Bulletin of Earthquake Engineering</i> , 2022, 20, 8445-8469.	2.3	2
130	Thermographic investigations and dynamic identification tests for non-destructive structural assessment and enhanced FE modelling of a historical iron-strengthened masonry church. <i>Journal of Civil Structural Health Monitoring</i> , 0, , .	2.0	0
131	Evaluation of the Seismic Vulnerability of Giotto's Bell Tower: Comparison of Different Methodologies. <i>International Journal of Architectural Heritage</i> , 2024, 18, 254-278.	1.7	2
132	Fracturing and collapse behavior of masonry vaulted structures: a lattice-discrete approach. <i>Procedia Structural Integrity</i> , 2023, 44, 1276-1283.	0.3	3
133	Empirical seismic vulnerability of Italian URM churches hit by the 2016-17 Central Italy earthquake sequence. <i>Procedia Structural Integrity</i> , 2023, 44, 91-98.	0.3	0
134	Analysis of the behavior of the masonry Medici tower resorting on a hybrid discrete-kinematic methodology. <i>Procedia Structural Integrity</i> , 2023, 44, 1640-1647.	0.3	2
135	Seismic assessment of typical historical masonry churches in the Banat region, Romania - Part II. <i>Procedia Structural Integrity</i> , 2023, 44, 2044-2051.	0.3	2
136	Collapse mechanisms of churches: typical recurrence rates and damage levels from the analysis of field data after the 2012 Emilia earthquake. <i>Procedia Structural Integrity</i> , 2023, 44, 1132-1139.	0.3	0
137	A comprehensive proposal for rehabilitation of historic Armenian church belonging to 16th century AD (Diyarbakır, Turkey). <i>Structures</i> , 2023, 50, 118-147.	1.7	0
138	Damage survey on churches: A new Observed Damage Database of past Italian earthquakes (Da.D.O.). <i>International Journal of Disaster Risk Reduction</i> , 2023, 87, 103595.	1.8	4
139	Seismic Assessment of the Archangeloi (Bağmelekler) Church in Kumyaka, Türkiye. <i>Buildings</i> , 2023, 13, 787.	1.4	0
140	Combining Architectural Conservation and Seismic Strengthening in the Wood-Based Retrofitting of a Monumental Timber Roof: The Case Study of St. Andrew's Church in Ceto, Brescia, Italy. <i>International Journal of Architectural Heritage</i> , 0, , 1-21.	1.7	1
143	Preliminary Assessment of a Historic Masonry Church Strengthened by Reinforced Concrete Elements During 1927-1930. The Case of Recoleta Dominica Basilica in Santiago, Chile. <i>RILEM Bookseries</i> , 2024, , 1134-1146.	0.2	0
144	Preventive Retrofitting Strategies for Archetype Buildings Representative of the Abruzzo Region. <i>RILEM Bookseries</i> , 2024, , 1147-1158.	0.2	0