Material loss at the taper junction of retrieved large hea replacements

Journal of Orthopaedic Research

31, 1677-1685

DOI: 10.1002/jor.22431

Citation Report

#	Article	IF	Citations
1	Does taper angle clearance influence fretting and corrosion damage at the headâ€“stem interface? A matched cohort retrieval study. Seminars in Arthroplasty, 2013, 24, 246-254.	0.3	61
2	Wear patterns of taper connections in retrieved large diameter metalâ€onâ€metal bearings. Journal of Orthopaedic Research, 2013, 31, 1116-1122.	1.2	101
3	Trunnionosis: A pain in the neck. World Journal of Orthopedics, 2013, 4, 161.	0.8	64
4	Do Retrieval Analysis and Blood Metal Measurements Contribute to Our Understanding of Adverse Local Tissue Reactions?. Clinical Orthopaedics and Related Research, 2014, 472, 3718-3727.	0.7	41
5	What is the Trouble With Trunnions?. Clinical Orthopaedics and Related Research, 2014, 472, 3652-3658.	0.7	110
6	The Relation Between Titanium Taper Corrosion and Cobalt-Chromium Bearing Wear in Large-Head Metal-on-Metal Total Hip Prostheses. Journal of Bone and Joint Surgery - Series A, 2014, 96, e157.	1.4	54
7	The Reliability of a Scoring System for Corrosion and Fretting, and Its Relationship to Material Loss of Tapered, Modular Junctions of Retrieved Hip Implants. Journal of Arthroplasty, 2014, 29, 1313-1317.	1.5	68
8	Utility of Modular Implants in Primary Total Hip Arthroplasty. Journal of Arthroplasty, 2014, 29, 657-658.	1.5	12
9	The Local Effects of Metal Corrosion in Total Hip Arthroplasty. Orthopedic Clinics of North America, 2014, 45, 9-18.	0.5	39
10	Repeated metal ion measurements in patients with high risk metal-on-metal hip replacement. International Orthopaedics, 2014, 38, 1353-1361.	0.9	40
11	Component Size Mismatch of Metal on Metal Hip Arthroplasty: An Avoidable Never Event. Journal of Arthroplasty, 2014, 29, 1629-1634.	1.5	10
12	Quantification of material loss from the neck piece taper junctions of a bimodular primary hip prosthesis. A retrieval study from 27 failed Rejuvenate bimodular hip arthroplasties. Bone and Joint Journal, 2015, 97-B, 1350-1357.	1.9	27
13	The effect of frictional torque and bending moment on corrosion at the taper interface. Bone and Joint Journal, 2015, 97-B, 463-472.	1.9	49
14	Assessing the material loss of the modular taper interface in retrieved metal-on-metal hip replacements. Surface Topography: Metrology and Properties, 2015, 3, 025002.	0.9	6
15	Volumetric assessment of material loss from retrieved cemented metal hip replacement stems. Tribology International, 2015, 89, 105-108.	3.0	6
16	Diagnostic utility of joint fluid metal ion measurement for histopathological findings in metal-on-metal hip replacements. BMC Musculoskeletal Disorders, 2015, 16, 393.	0.8	24
17	Shorter, rough trunnion surfaces are associated with higher taper wear rates than longer, smooth trunnion surfaces in a contemporary large head metalâ€onâ€metal total hip arthroplasty system. Journal of Orthopaedic Research, 2015, 33, 1868-1874.	1.2	63
18	The Prevention and Treatment of Dislocation following Total Hip Arthroplasty: Efforts to Date and Future Strategies. HIP International, 2015, 25, 388-392.	0.9	27

#	Article	IF	Citations
19	Complications Related to Metal-on-Metal Articulation in Trapeziometacarpal Joint Total Joint Arthroplasty. Journal of Functional Biomaterials, 2015, 6, 318-327.	1.8	7
20	Quantification of the Contact Area at the Head-Stem Taper Interface of Modular Hip Prostheses. PLoS ONE, 2015, 10, e0135517.	1.1	31
21	Is There Material Loss at the Backside Taper in Modular CoCr Acetabular Liners?. Clinical Orthopaedics and Related Research, 2015, 473, 275-285.	0.7	30
22	Clinically Significant Corrosion at the Head-Neck Taper Interface in Total Hip Arthroplasty: A Systematic Review and Case Series. HIP International, 2015, 25, 7-14.	0.9	37
23	The Evolution of the Trunnion. HIP International, 2015, 25, 2-6.	0.9	8
24	Characterisation of the oxide film on the taper interface from retrieved large diameter metal on polymer modular total hip replacements. Tribology International, 2015, 89, 86-96.	3.0	9
25	Basic Principles and Uniform Terminology for the Head-Neck Junction in Hip Replacement. HIP International, 2015, 25, 115-119.	0.9	21
26	Influence of stem type on material loss at the metal-on-metal pinnacle taper junction. Proceedings of the Institution of Mechanical Engineers, Part H: Journal of Engineering in Medicine, 2015, 229, 91-97.	1.0	30
27	Revision of Articular Surface Replacement (ASR) Total Hip Arthroplasty: Correlation of Perioperative Data and Early Post-Revision Outcome Results. Journal of Arthroplasty, 2015, 30, 1607-1617.	1.5	8
28	Femoral diameter and stem type are independent risk factors for ARMD in the Large-headed ASR THR group. BMC Musculoskeletal Disorders, 2015, 16, 118.	0.8	14
29	Sequelae of large-head metal-on-metal hip arthroplasties. EFORT Open Reviews, 2016, 1, 345-353.	1.8	15
30	Prevalence of Failure due to Adverse Reaction to Metal Debris in Modern, Medium and Large Diameter Metal-on-Metal Hip Replacements â€“ The Effect of Novel Screening Methods: Systematic Review and Metaregression Analysis. PLoS ONE, 2016, 11, e0147872.	1.1	37
31	Large-diameter total hip arthroplasty modular heads require greater assembly forces for initial stability. Bone and Joint Research, 2016, 5, 338-346.	1.3	21
32	The effect of using components from different manufacturers on the rate of wear and corrosion of the headâ€“stem taper junction of metal-on-metal hip arthroplasties. Bone and Joint Journal, 2016, 98-B, 917-924.	1.9	12
33	The clinical implications of metal debris release from the taper junctions and bearing surfaces of metal-on-metal hip arthroplasty. Bone and Joint Journal, 2016, 98-B, 925-933.	1.9	35
34	Metal-on-Metal Total Hip Arthroplasty at Five to Twelve Years Follow-Up: A Concise Follow-Up of a Previous Report. Journal of Arthroplasty, 2016, 31, 1773-1778.	1.5	13
35	The Relationship Between Cobalt/Chromium Ratios and the High Prevalence of Head-Stem Junction Corrosion in Metal-on-Metal Total Hip Arthroplasty. Journal of Arthroplasty, 2016, 31, 1123-1127.	1.5	50
36	Leukocyte Esterase: Metal-on-Metal Failure and Periprosthetic JointÂInfection. Journal of Arthroplasty, 2016, 31, 2260-2263.	1.5	19

#	Article	IF	Citations
37	Influence of particulate and dissociated metal-on-metal hip endoprosthesis wear on mesenchymal stromal cells inÂvivo and inÂvitro. Biomaterials, 2016, 98, 31-40.	5.7	62
38	Evidence for the dissolution of molybdenum during tribocorrosion of CoCrMo hip implants in the presence of serum protein. Acta Biomaterialia, 2016, 45, 410-418.	4.1	30
39	Medium-Term Results following Large Diameter Metal-on-Metal Total HIP Arthroplasty: Increasing Failure after 6 Years. HIP International, 2016, 26, 226-232.	0.9	7
40	Cobalt serum levels differ in well functioning Birmingham resurfacing and Birmingham modular THA. Archives of Orthopaedic and Trauma Surgery, 2016, 136, 715-721.	1.3	11
41	Trunnionosis in total hip arthroplasty: a review. Journal of Orthopaedics and Traumatology, 2016, 17, 1-6.	1.0	100
42	Ceramic Heads Decrease Metal Release Caused by Head-taper Fretting and Corrosion. Clinical Orthopaedics and Related Research, 2016, 474, 985-994.	0.7	69
43	Explant Analysis from a Patient Exhibiting Rapid Acceleration of Parkinson Disease Symptoms and Hypercobaltemia Following Metal-on-Metal Total Hip Arthroplasty. JBJS Case Connector, 2016, 6, e45.	0.1	11
44	Clinical significance of corrosion of cemented femoral stems in metal-on-metal hips: a retrieval study. International Orthopaedics, 2016, 40, 2247-2254.	0.9	17
45	Higher Blood Cobalt and Chromium Levels in Patients With Unilateral Metal-on-Metal Total Hip Arthroplasties Compared to Hip Resurfacings. Journal of Arthroplasty, 2016, 31, 1261-1266.	1.5	23
46	Elevated Intra-Articular Cobalt and Chromium Levels in Mechanically Assisted Crevice Corrosion in Metal-on-Polyethylene Total Hip Arthroplasty. Journal of Arthroplasty, 2017, 32, 1654-1658.	1.5	34
47	A large taper mismatch is one of the key factors behind high wear rates and failure at the taper junction of total hip replacements: A finite element wear analysis. Journal of the Mechanical Behavior of Biomedical Materials, 2017, 69, 257-266.	1.5	56
48	Clinically insignificant trunnionosis in large-diameter metal-on-polyethylene total hip arthroplasty. Bone and Joint Research, 2017, 6, 52-56.	1.3	18
49	Assessment of the equivalence of a generic to a branded femoral stem. Bone and Joint Journal, 2017, 99-B, 310-316.	1.9	6
50	Comparative study of material loss at the taper interface in retrieved metal-on-polyethylene and metal-on-metal femoral components from a single manufacturer. Proceedings of the Institution of Mechanical Engineers, Part H: Journal of Engineering in Medicine, 2017, 231, 683-690.	1.0	2
51	Response to Letter to the Editor on â€œFactors Associated With Trunnionosis in the Metal-on-Metal Pinnacle Hipâ€• Journal of Arthroplasty, 2017, 32, 1045-1046.	1.5	2
52	Investigation of Taper Failure in a Contemporary Metal-on-Metal Hip Arthroplasty System Through Examination of Unused and Explanted Prostheses. Journal of Bone and Joint Surgery - Series A, 2017, 99, 427-436.	1.4	21
53	Retrieval analysis of metal and ceramic femoral heads on a single CoCr stem design. Bone and Joint Research, 2017, 6, 345-350.	1.3	11
54	Assessment of Corrosion, Fretting, and Material Loss of Retrieved Modular Total Knee Arthroplasties. Journal of Arthroplasty, 2017, 32, 2279-2284.	1.5	9

#	Article	IF	Citations
55	Wear of dual-mobility cups: a review article. International Orthopaedics, 2017, 41, 625-633.	0.9	42
56	A comparison study of stem taper material loss at similar and mixed metal head-neck taper junctions. Bone and Joint Journal, 2017, 99-B, 1304-1312.	1.9	16
57	Mild or moderate renal insufficiency does not increase circulating levels of cobalt and chromium in patients with metal-on-metal hip arthroplasty. Bone and Joint Journal, 2017, 99-B, 1147-1152.	1.9	8
58	Comparison of metal ion levels in patients with hip resurfacing versus total hip arthroplasty. Journal of Orthopaedics, 2017, 14, 561-564.	0.6	6
59	Lack of evidenceâ€"the anti-stepwise introduction of metal-on-metal hip replacements. Monthly Notices of the Royal Astronomical Society: Letters, 2017, 88, 478-483.	1.2	10
60	Factors Associated With Trunnionosis in the Metal-on-Metal Pinnacle Hip. Journal of Arthroplasty, 2017, 32, 286-290.	1.5	42
61	Clinical Cold Welding of the Modular Total Hip Arthroplasty Prosthesis. Journal of Arthroplasty, 2017, 32, 610-615.	1.5	7
62	Letter to the Editor on â€œFactors Associated With Trunnionosis in the Metal-on-Metal Pinnacle Hipâ€• Journal of Arthroplasty, 2017, 32, 1044.	1.5	2
63	Damage Patterns at the Head-Stem Taper Junction Helps Understand the Mechanisms of Material Loss. Journal of Arthroplasty, 2017, 32, 291-295.	1.5	21
64	Variation in taper surface roughness for a single design effects the wear rate in total hip arthroplasty. Journal of Orthopaedic Research, 2017, 35, 1784-1792.	1.2	17
65	Trunnionosis: Is it really a problem?. Seminars in Arthroplasty, 2017, 28, 206-210.	0.3	3
66	Outcome of Revision Arthroplasty for Failed Metal-On-Metal Total Hip Replacements; is there a Relation with Metal Ions?. HIP International, 2017, 27, 235-240.	0.9	4
67	Technical note: Comparison of metal-on-metal hip simulator wear measured by gravimetric, CMM and optical profiling methods. Surface Topography: Metrology and Properties, 2018, 6, 014002.	0.9	0
68	Effect of Bearing Type on Taper Material Loss in Hips From 1 Manufacturer. Journal of Arthroplasty, 2018, 33, 1588-1593.	1.5	7
69	Predictive factors for metal ion levels in metal-on-metal total hip arthroplasty. Archives of Orthopaedic and Trauma Surgery, 2018, 138, 281-286.	1.3	8
70	Trunnion corrosion. Bone and Joint Journal, 2018, 100-B, 44-49.	1.9	68
71	Five Hundred Fifty-five Retrieved Metal-on-metal Hip Replacements of a Single Design Show a Wide Range of Wear, Surface Features, and Histopathologic Reactions. Clinical Orthopaedics and Related Research, 2018, 476, 261-278.	0.7	22
72	Does the Additional Articulation in Retrieved Bipolar Hemiarthroplasty Implants Decrease Trunnionosis Compared to Total Hip Arthroplasty?. Journal of Arthroplasty, 2018, 33, 268-272.	1.5	6

#	Article	IF	Citations
73	Wear performance of retrieved metal-on-metal Pinnacle hip arthroplasties implanted before and after 2007. Bone and Joint Research, 2018, 7, 595-600.	1.3	5
74	Understanding outcomes and toxicological aspects of second generation metal-on-metal hip implants: a state-of-the-art review. Critical Reviews in Toxicology, 2018, 48, 839-887.	1.9	31
75	The Distribution and Severity of Corrosion Damage at Eight Distinct Zones of Metallic Femoral Stem Implants. Metals, 2018, 8, 840.	1.0	6
76	Retrieval Findings of Recalled Dual-Taper Hips. Journal of Bone and Joint Surgery - Series A, 2018, 100, 1661-1672.	1.4	12
77	Association between periprosthetic tissue metal content, whole blood and synovial fluid metal ion levels and histopathological findings in patients with failed metal-on-metal hip replacement. PLoS ONE, 2018, 13, e0197614.	1.1	25
78	Implant Failure After Motec Wrist Joint Prosthesis DueÂto Failure of Ball and Socket-Type Articulationâ€"Two Patients With Adverse Reaction toÂMetal Debris and Polyether Ether Ketone. Journal of Hand Surgery, 2018, 43, 1044.e1-1044.e4.	0.7	17
79	Profound Trunnion Wear Resulting in Femoral Head-Neck Dissociation in Total Hip Arthroplasty. Case Reports in Orthopedics, 2018, 2018, 1-4.	0.1	5
80	The effect of the inflammatory species hypochlorous acid on the corrosion and surface damage of Tiâ€6Alâ€4V and CoCrMo alloys. Journal of Biomedical Materials Research - Part A, 2018, 106, 3185-3194.	2.1	15
81	Influence of Cobalt Ions on Collagen Gel Formation and Their Interaction with Osteoblasts. ACS Omega, 2018, 3, 10129-10138.	1.6	14
82	A case of bilateral hip mechanically assisted crevice corrosion after staged total hip arthroplasty. Arthroplasty Today, 2018, 4, 261-265.	0.8	2
83	Revision for adverse local tissue reaction following metal-on-polyethylene total hip arthroplasty is associated with a high risk of early major complications. Bone and Joint Journal, 2018, 100-B, 720-724.	1.9	31
84	The effect of altering head length on corrosion using a material loss method. HIP International, 2019, 29, 368-372.	0.9	4
85	Retrieval Analysis And Principal Variable Analysis Of 127 M2a-38â€¯Mmâ„¢ Metal On Metal Hip Replacements. Biotribology, 2019, 19, 100102.	0.9	0
86	Is There Material Loss at the Conical Junctions of Modular Components for Total Knee Arthroplasty?. Journal of Arthroplasty, 2019, 34, 2479-2486.	1.5	9
87	Host-specific factors affect the pathogenesis of adverse reaction to metal debris. BMC Musculoskeletal Disorders, 2019, 20, 195.	0.8	6
88	Changes in the morphology of microgrooved stem tapers with differing assembly conditions. Biotribology, 2019, 18, 100096.	0.9	6
89	Wear at the taperâ€trunnion junction of contemporary ceramicâ€onâ€ceramic hips shown in a multistation hip simulator. Journal of Biomedical Materials Research - Part B Applied Biomaterials, 2019, 107, 1199-1209.	1.6	14
90	Femoral head material loss at the head-neck junction in total hip arthroplasty: the effect of head size, stem material and stem offset. HIP International, 2019, 29, 647-651.	0.9	5

#	Article	IF	Citations
91	Hip simulator testing of the taperâ€trunnion junction and bearing surfaces of contemporary metalâ€onâ€crossâ€linkedâ€polyethylene hip prostheses. Journal of Biomedical Materials Research - Part B Applied Biomaterials, 2020, 108, 156-166.	1.6	12
92	Histopathological patterns seen around failed metalâ€onâ€metal hip replacements: Cluster and latent class analysis of patterns of failure. Journal of Biomedical Materials Research - Part B Applied Biomaterials, 2020, 108, 1085-1096.	1.6	3
93	Gross trunnion failure in metal on polyethylene total hip arthroplastyâ€"a systematic review of literature. International Orthopaedics, 2020, 44, 609-621.	0.9	23
94	Does diametrical clearance influence the wear of Pinnacle hip implants?. Bone and Joint Research, 2020, 9, 515-523.	1.3	4
95	Taper corrosion: a complication of total hip arthroplasty. EFORT Open Reviews, 2020, 5, 776-784.	1.8	21
96	Assessing the quality of inspection for tapered aircraft fastener holes using an engineerâ€™s blue contact test. Precision Engineering, 2020, 63, 62-67.	1.8	2
97	A comparative study on the physicochemical characteristics of nanoparticles released in vivo from <scp>CoCrMo</scp> tapers and cementâ€"stem interfaces of total hip replacements. Journal of Biomedical Materials Research - Part B Applied Biomaterials, 2020, 108, 3311-3322.	1.6	0
98	Does modularity of metal-on-metal hip implants increase cobalt: chromium ratio?. HIP International, 2021, 31, 109-114.	0.9	1
99	Semiâ€quantitative histology confirms that the macrophage is the predominant cell type in metalâ€onâ€metal hip tissues. Journal of Orthopaedic Research, 2021, , .	1.2	6
100	Comparison and appraisal of techniques for the determination of material loss from tapered orthopaedic surfaces. Wear, 2021, 478-479, 203903.	1.5	1
101	Validation of an Optical Coordinate Measuring Machine for the Measurement of Wear at the Taper Interface in Total Hip Replacement. , 2015, , 362-378.		6
102	Factors Related to Imprinting Corrosion in Modular Head-Neck Junctions. , 2015, , 83-98.		6
103	Microgrooved Surface Topography Does Not Influence Fretting Corrosion of Tapers in Total Hip Arthroplasty: Classification and Retrieval Analysis. , 2015, , 99-112.		6
104	Trunnion Corrosion causing Failure in Metal-on-Polyethylene Total Hip Arthroplasty with Monolithic Femoral Components. Reconstructive Review, 2016, 6, .	0.1	7
105	Hip Arthroplasty Pseudotumors: Pathogenesis, Imaging, and Clinical Decision Making. Journal of Clinical Imaging Science, 2016, 6, 17.	0.4	34
106	Metallic debris from metal-on-metal total hip arthroplasty regulates periprosthetic tissues. World Journal of Orthopedics, 2014, 5, 660.	0.8	41
107	Diagnosis and Management of Adverse Local Tissue Reactions Secondary to Products of Tribocorrosion. , 2015, , 396-409.		0
108	Metrology for Dual Taper Total Hip Arthroplasty. , 2015, , 164-180.		2

#	Article	IF	Citations
109	Method for Characterization of Material Loss from Modular Head-Stem Taper Surfaces of Hip Replacement Devices. , 2015, , 132-146.		2
110	Fretting Corrosion and Modularity: A Critical Review of the Literature and Three Registries. , 2015, , 34-44.		0
111	Methods for Characterization of Edge Wear in Ceramic-on-Ceramic Acetabular Cups. , 2018, , 156-172.		0
112	Using Coordinate Measuring Machine Validated with White Light Interferometry to Identify Contributors to Material Loss Due to Corrosion of Total Hip Replacement Modular Junctions. , 2018, , 118-130.		3
113	Characterization of Material Loss from Femoral Stem Taper Surfaces through Development of a Responsive Morphological Filtering Technique. , 2018, , 173-190.		0
114	Electrochemical Testing of Modular Taper Junctions: Effect of Assembly Force and Head Offset. , 2019, , 114-136.		1
115	Metal-on-metal total hip arthroplasty: does increasing modularity affect clinical outcome?. HIP International, 2020, , 112070002097927.	0.9	1
116	In vitro testing for hip head-neck taper tribocorrosion: A review of experimental methods. Proceedings of the Institution of Mechanical Engineers, Part H: Journal of Engineering in Medicine, 2022, , 095441192210745.	1.0	1
117	Effect of surface topography and residual stress on the taper connection stability in total hip arthroplasty. Journal of the Mechanical Behavior of Biomedical Materials, 2022, 128, 105119.	1.5	2
118	Taper corrosion in total hip arthroplasty â€“ How to assess and which design features are crucial?. Journal of the Mechanical Behavior of Biomedical Materials, 2022, 133, 105307.	1.5	1
119	Preâ€clinical evaluation of frettingâ€corrosion at stemâ€head and stemâ€cement interfaces of hip implants using in vitro and in silico models. Journal of Biomedical Materials Research - Part B Applied Biomaterials, 2022, 110, 2521-2532.	1.6	0