

Na Zhang

List of Publications by Year in descending order

Source: <https://exaly.com/author-pdf/7127824/publications.pdf>

Version: 2024-02-01

22
papers

881
citations

840728

11
h-index

752679

20
g-index

22
all docs

22
docs citations

22
times ranked

745
citing authors

#	ARTICLE	IF	CITATIONS
1	Utilization of red mud in cement production: a review. <i>Waste Management and Research</i> , 2011, 29, 1053-1063.	3.9	167
2	Intermediate-calcium based cementitious materials prepared by MSWI fly ash and other solid wastes: hydration characteristics and heavy metals solidification behavior. <i>Journal of Hazardous Materials</i> , 2018, 349, 262-271.	12.4	147
3	Early-age characteristics of red mud-coal gangue cementitious material. <i>Journal of Hazardous Materials</i> , 2009, 167, 927-932.	12.4	139
4	Cementitious activity of iron ore tailing and its utilization in cementitious materials, bricks and concrete. <i>Construction and Building Materials</i> , 2021, 288, 123022.	7.2	93
5	Pozzolanic behaviour of compound-activated red mud-coal gangue mixture. <i>Cement and Concrete Research</i> , 2011, 41, 270-278.	11.0	92
6	Evaluation of blends bauxite-calcination-method red mud with other industrial wastes as a cementitious material: Properties and hydration characteristics. <i>Journal of Hazardous Materials</i> , 2011, 185, 329-335.	12.4	68
7	Preparation and microstructural characterization of a novel 3D printable building material composed of copper tailings and iron tailings. <i>Construction and Building Materials</i> , 2020, 249, 118779.	7.2	44
8	Correlation between ²⁹ Si polymerization and cementitious activity of coal gangue. <i>Journal of Zhejiang University: Science A</i> , 2009, 10, 1334-1340.	2.4	33
9	Electron probe microanalysis for revealing occurrence mode of scandium in Bayer red mud. <i>Rare Metals</i> , 2017, 36, 295-303.	7.1	22
10	Preparation and Photocatalytic Property of TiO ₂ Columnar Nanostructure Films. <i>Materials Transactions</i> , 2011, 52, 1939-1942.	1.2	15
11	C-A-S-H Gel and Pore Structure Characteristics of Alkali-Activated Red Mud-Iron Tailings Cementitious Mortar. <i>Materials</i> , 2022, 15, 112.	2.9	14
12	New attempt to produce red mud-iron tailing based alkali-activated mortar: Performance and microstructural characteristics. <i>Journal of Building Engineering</i> , 2021, 43, 103222.	3.4	10
13	Corrosion behavior of steel rebar in coal gangue-based mortars. <i>Journal of Zhejiang University: Science A</i> , 2010, 11, 382-388.	2.4	8
14	Effect of Electrolytic Manganese Residue in Fly Ash-Based Cementitious Material: Hydration Behavior and Microstructure. <i>Materials</i> , 2021, 14, 7047.	2.9	8
15	A quantitative study of chemical kinetics for the synthesis of doped oxide nanocrystals using FTIR. <i>Scientific Reports</i> , 2015, 4, 4353.	3.3	6
16	Electrospun Polyphenylquinoxaline Ultrathin Non-woven Fibrous Membranes with Excellent Thermal and Alkaline Resistance: Preparation and Characterization. <i>Fibers and Polymers</i> , 2019, 20, 2485-2492.	2.1	4
17	Electrospun polyphenylquinoxaline fibrous membrane: a versatile filtering medium for separation of highly alkaline aqueous red mud pollutant. <i>Journal of Polymer Research</i> , 2020, 27, 1.	2.4	4
18	Photocatalysis in alkali activated cementitious materials. <i>Journal of Building Engineering</i> , 2022, 46, 103749.	3.4	3

#	ARTICLE	IF	CITATIONS
19	High-value utilisation of ceramic waste powder in PVC-based composite and basalt fibre reinforcement effect on its performance. <i>Ceramics International</i> , 2022, , .	4.8	2
20	Mortar Designed from Red Mud with Iron Tailings and Moulded by 3D Printing. <i>Bulletin of Environmental Contamination and Toxicology</i> , 2022, 109, 95-100.	2.7	2
21	The effect of HfO ₂ second phase in Fe films upon ion irradiation. <i>Frontiers of Materials Science in China</i> , 2010, 4, 193-196.	0.5	0
22	Reply to the comments by Venkata Siva Naga Sai Goli and Devendra Narain Singh of the paper "Incorporation of Xuan-paper waste residue in red mud/waste polyethylene composites". <i>Journal of Hazardous Materials</i> , 2021, 404, 124161.	12.4	0