Shen-en Chen

List of Publications by Year in descending order

Source: https://exaly.com/author-pdf/5242664/publications.pdf

Version: 2024-02-01

38	876	13	29
papers	citations	h-index	g-index
39	39	39	1034
all docs	docs citations	times ranked	citing authors

#	Article	IF	CITATIONS
1	The Challenges of Reusing Mining and Mineral-Processing Wastes. Science, 2012, 337, 702-703.	12.6	300
2	Compaction's Impacts on Urban Storm-Water Infiltration. Journal of Irrigation and Drainage Engineering - ASCE, 2008, 134, 652-658.	1.0	125
3	Monitoring the behavior of segment joints in a shield tunnel using distributed fiber optic sensors. Structural Control and Health Monitoring, 2018, 25, e2056.	4.0	60
4	Observations and Modeling of Coastal Boulder Transport and Loading During Super Typhoon Haiyan. Coastal Engineering Journal, 2016, 58, 1640004-1-1640004-25.	1.9	53
5	Experimental investigation on dynamic characterization and seismic control performance of a TLPD system. Structural Design of Tall and Special Buildings, 2017, 26, e1350.	1.9	39
6	Bridge Clearance Evaluation Based on Terrestrial LIDAR Scan. Journal of Performance of Constructed Facilities, 2012, 26, 469-477.	2.0	32
7	Reliability analysis of bridge evaluations based on 3D Light Detection and Ranging data. Structural Control and Health Monitoring, 2013, 20, 1397-1409.	4.0	28
8	Subsidence Mechanism and Stability Assessment Methods for Partial Extraction Mines for Sustainable Development of Mining Cities—A Review. Sustainability, 2018, 10, 113.	3.2	28
9	Long-Term Stability Evaluation and Pillar Design Criterion for Room-and-Pillar Mines. Energies, 2017, 10, 1644.	3.1	25
10	An improved method for long-term stability evaluation of strip mining and pillar design. International Journal of Rock Mechanics and Minings Sciences, 2018, 107, 25-30.	5.8	24
11	Surface damage quantification of postearthquake building based on terrestrial laser scan data. Structural Control and Health Monitoring, 2018, 25, e2210.	4.0	21
12	Integrated distributed fiber optic sensing technology-based structural monitoring of the pound lock. Structural Control and Health Monitoring, 2017, 24, e1954.	4.0	19
13	Mine Size Effects on Coal Pillar Stress and Their Application for Partial Extraction. Sustainability, 2018, 10, 792.	3.2	15
14	Comparative study of bridge management programmes and practices in the USA and China. Structure and Infrastructure Engineering, 2014, 10, 577-588.	3.7	14
15	Small multi-turn coils based on transient electromagnetic method for coal mine detection. Journal of Applied Geophysics, 2019, 169, 165-173.	2.1	12
16	A framework for holistic designs of power line systems based on lessons learned from Super Typhoon Haiyan. Sustainable Cities and Society, 2017, 35, 350-364.	10.4	11
17	Evaluation of residual strength and durability aspect of concrete cube exposed to elevated temperature. Journal of Sustainable Cement-Based Materials, 2017, 6, 231-253.	3.1	10
18	An inversion of transient electromagnetic data from a conical source. Applied Geophysics, 2018, 15, 545-555.	0.6	9

#	Article	IF	CITATIONS
19	Dynamic Study of a Rooftop Vertical Axis Wind Turbine Tower Based on an Automated Vibration Data Processing Algorithm. Energies, 2018, 11, 3135.	3.1	8
20	Modal Characteristics of Two Operating Power Transmission Poles. Shock and Vibration, 2010, 17, 551-561.	0.6	7
21	The thermodynamic properties variation of cemented clay after treatment at high temperatures. Construction and Building Materials, 2018, 182, 523-529.	7.2	6
22	Forensic engineering education reform. Proceedings of the Institution of Civil Engineers: Forensic Engineering, 2013, 166, 9-16.	0.5	5
23	Transient Electromagnetic Response With a Ramp Current Excitation Using Conical Source. IEEE Access, 2019, 7, 63829-63836.	4.2	5
24	Prototyping rail track for micro-people movers using additive manufacturing: Failure topology characterization. Construction and Building Materials, 2021, 281, 122623.	7.2	4
25	An Empirical Model for Geopolymer Reactions Involving Fly Ash and GGBS. Advances in Materials Science and Engineering, 2022, 2022, 1-13.	1.8	3
26	An Analysis of Local and Combined (Global) Scours on Piers-on-Bank Bridges. CivilEng, 2022, 3, 1-20.	1.4	3
27	Axial and transverse characterizations of ceramic candle filters. Fuel, 2008, 87, 2807-2816.	6.4	2
28	3D-RVSP experimental study above a carbonate outcrop for coal resource exploration. Acta Geophysica, 2019, 67, 95-107.	2.0	2
29	Posthurricane Investigation of a Critical Component toward Improved Grid Resiliency in Puerto Rico. Journal of Performance of Constructed Facilities, 2020, 34, 02520001.	2.0	2
30	Nondestructive Quality Assurance of Ceramic Filters Using Noncontact Dynamic Characterization. Journal of Nondestructive Evaluation, 2005, 24, 55-66.	2.4	1
31	Remote sensing techniques for geo-problem applications. Japanese Geotechnical Society Special Publication, 2016, 2, 207-211.	0.2	1
32	An Energy Demodulation Based Fiber Optic Sensing System for Landslide Early-Warning. Applied Sciences (Switzerland), 2017, 7, 699.	2.5	1
33	Resiliency of Power Grid Infrastructure Under Extreme Hazards - Observations and Lessons Learned from Hurricane Maria in Puerto Rico. Sustainable Civil Infrastructures, 2021, , 1-17.	0.2	1
34	Ash pond erosion process monitoring using LiDAR scans. Japanese Geotechnical Society Special Publication, 2016, 2, 1051-1055.	0.2	0
35	Structural Assessment of Cyclone Hudhud in Vizag, Andhra Pradesh. Journal of Performance of Constructed Facilities, 2020, 34, 04020099.	2.0	0
36	Multi-hole joint acquisition of a 3D-RVSP in a karst area: Case study in the Wulunshan Coal Field, China. Applied Geophysics, 2020, 17, 37-53.	0.6	0

SHEN-EN CHEN

#	Article	IF	CITATIONS
37	Two-Story Residential Structure Damages after the 2020 Puerto Rico Earthquake. Journal of Performance of Constructed Facilities, 2022, 36, .	2.0	O
38	Modeling of Progressive Scouring of a Pier-on-Bank. CivilEng, 2022, 3, 365-384.	1.4	0