Satoshi Goto

List of Publications by Year in descending order

Source: https://exaly.com/author-pdf/5452361/publications.pdf Version: 2024-02-01



SATOSHI COTO

#	Article	IF	CITATIONS
1	Torrent rainfall-induced large-scale karst limestone slope collapse at Khanh waterfall, Hoa Binh Province, Vietnam. Geoenvironmental Disasters, 2022, 9, .	3.6	7
2	Gravitational deformation as a precursor of shallow landslide within tephra-covered slope deposits in the Aso caldera, Japan. Journal of the Japan Landslide Society, 2017, 54, 199-204.	0.1	5
3	Geomorphological setting of shallow landslides by heavy rainfall on tephra-covered slopes of Aso Volcano, southwest Japan. Journal of the Japan Landslide Society, 2019, 56, 218-226.	0.1	5
4	Characteristics of tuff breccia-andesite in diverse mechanisms of landslides in Oita Prefecture, Kyushu, Japan. Geoenvironmental Disasters, 2021, 8, .	3.6	3
5	Introduction of the special issue on "Toward the prediction of shallow landslides induced by heavy rainfalls on tephra-covered slopes― Journal of the Japan Landslide Society, 2019, 56, 211-217.	0.1	3
6	Evaluation of landslide susceptibility by slope stability analysis using an estimated distribution of tephra depositsï¼A case study in the northeastern part of Aso caldera5 Journal of the Japan Landslide Society, 2019, 56, 240-249.	0.1	3
7	Strength characteristics of gravitationally deformed slope deposits of tephra and kuroboku soils in the Aso caldera, Japan ï¼Application of revised vane-shear-cone test for estimating shear strength5 Journal of the Japan Landslide Society, 2019, 56, 250-253.	0.1	3
8	Sliding layer estimation of shallow landslides on Aso volcanic mountains in Japan based on tephra layer-physical properties of soil. Geoenvironmental Disasters, 2020, 7, .	3.6	2
9	Landslide disasters induced by the Northern Kyushu heavy rainfall in July 2017. Journal of the Japan Landslide Society, 2017, 54, 225-228.	0.1	2