

?? ?

List of Publications by Year in Descending Order

Source: <https://exaly.com/author-pdf/8407015/-publications-by-year.pdf>

Version: 2024-04-26

This document has been generated based on the publications and citations recorded by exaly.com. For the latest version of this publication list, visit the link given above.

The third column is the impact factor (IF) of the journal, and the fourth column is the number of citations of the article.

11
papers

88
citations

6
h-index

9
g-index

12
ext. papers

125
ext. citations

2
avg, IF

2.57
L-index

#	Paper	IF	Citations
11	A numerical method of combined SPF-MEM-LBM on the rockfall-induced surge and its application. <i>Journal of Mountain Science</i> , 2022 , 19, 167-183	2.1	0
10	Deformation and failure of a high-steep slope induced by multi-layer coal mining. <i>Journal of Mountain Science</i> , 2020 , 17, 2942-2960	2.1	2
9	Mechanism of toppling and deformation in hard rock slope: a case of bank slope of Hydropower Station, Qinghai Province, China. <i>Journal of Mountain Science</i> , 2019 , 16, 924-934	2.1	8
8	Impact of polymer mixtures on the stabilization and erosion control of silty sand slope. <i>Journal of Mountain Science</i> , 2019 , 16, 470-485	2.1	9
7	Evaluation of the possible slip surface of a highly heterogeneous rock slope using dynamic reduction method. <i>Journal of Mountain Science</i> , 2018 , 15, 672-684	2.1	4
6	Centrifuge model test of an irrigation-induced loess landslide in the Heifangtai loess platform, Northwest China. <i>Journal of Mountain Science</i> , 2018 , 15, 130-143	2.1	25
5	Distribution and mechanism of gently dipping fractures subjected to river incision: A case study from Nujiang River, China. <i>Journal of Mountain Science</i> , 2018 , 15, 211-224	2.1	3
4	Geological analysis of gravitational rock slope deformation: a case from Nujiang River, China. <i>Journal of Mountain Science</i> , 2017 , 14, 2122-2133	2.1	2
3	Rolling motion behavior of rockfall on gentle slope: an experimental approach. <i>Journal of Mountain Science</i> , 2017 , 14, 1550-1562	2.1	8
2	Distribution and quantitative zonation of unloading cracks at a proposed large hydropower station dam Site. <i>Journal of Mountain Science</i> , 2017 , 14, 2106-2121	2.1	6
1	Deep-seated large-scale toppling failure in metamorphic rocks: a case study of the Erguxi slope in southwest China. <i>Journal of Mountain Science</i> , 2016 , 13, 2094-2110	2.1	20