## Comprehensive FE numerical insight into Finale Emilia Romagna seismic sequence: Damage causes and seismic

Engineering Structures 117, 397-421 DOI: 10.1016/j.engstruct.2016.02.048

**Citation Report** 

#	Article	IF	CITATIONS
1	Assessment of seismic behaviour of heritage masonry buildings using numerical modelling. Journal of Building Engineering, 2016, 8, 29-47.	1.6	128
2	Analysis of damage mechanisms suffered by Italian fortified buildings hit by earthquakes in the last 40Âyears. Bulletin of Earthquake Engineering, 2017, 15, 5139-5166.	2.3	19
3	Global analyses of historical masonry buildings: Equivalent frame vs. 3D solid models. AIP Conference Proceedings, 2017, , .	0.3	7
4	Realistic behavior of infilled steel frames in seismic events: experimental and analytical study. Bulletin of Earthquake Engineering, 2017, 15, 5365-5392.	2.3	14
5	An Investigation of the Seismic Behaviour of an Ancient Masonry Bastion Using Non-Destructive and Numerical Methods. Experimental Mechanics, 2017, 57, 245-259.	1.1	16
6	Hybrid parallel approach to homogenization of transport processes in masonry. Advances in Engineering Software, 2017, 113, 25-33.	1.8	7
7	An innovative numerical modeling strategy for the structural analysis of historical monumental buildings. Engineering Structures, 2017, 132, 229-248.	2.6	135
8	Masonry structures built with fictile tubules: Experimental and numerical analyses. AIP Conference Proceedings, 2017, , .	0.3	10
9	Earthquake response of heavily damaged historical masonry mosques after restoration. Natural Hazards and Earth System Sciences, 2017, 17, 1811-1821.	1.5	8
10	Two-step advanced numerical approach for the design of low-cost unbonded fiber reinforced elastomeric seismic isolation systems in new masonry buildings. Engineering Failure Analysis, 2018, 90, 380-396.	1.8	41
11	A kinematic limit analysis approach for seismic retrofitting of masonry towers through steel tie-rods. Engineering Structures, 2018, 160, 212-228.	2.6	50
12	Stability analysis of leaning historic masonry structures. Automation in Construction, 2018, 92, 199-213.	4.8	37
13	Collapse investigation of the Arquata del Tronto medieval fortress after the 2016 Central Italy seismic sequence. Journal of Building Engineering, 2018, 18, 245-251.	1.6	27
14	Numerical insights on the seismic behavior of a non-isolated historical masonry tower. Bulletin of Earthquake Engineering, 2018, 16, 933-961.	2.3	80
15	Evaluations on the seismic vulnerability of masonry churches: A case study in Amantea (Cosenza –) Tj ETQqO O	0rgBT /O	verlock 10 Tf
16	Investigation of the structural behaviour of a masonry castle by considering the actual damage. International Journal of Masonry Research and Innovation, 2018, 3, 1.	0.3	6
17	Simple limit analysis approach for the optimal strengthening of existing masonry towers. AIP Conference Proceedings, 2018, , .	0.3	3

18Integrated approach for seismic vulnerability analysis of historic massive defensive structures.1.53118Journal of Cultural Heritage, 2019, 35, 86-98.1.531

#	Article	IF	CITATIONS
19	Hybrid seismic base isolation of a historical masonry church using unbonded fiber reinforced elastomeric isolators and shape memory alloy wires. Engineering Structures, 2019, 196, 109281.	2.6	41
20	A new multi-control-point pushover methodology for the seismic assessment of historic masonry buildings. Journal of Building Engineering, 2019, 26, 100926.	1.6	20
21	Seismic vulnerability of ancient masonry buildings: The case study of low-rise towers. AIP Conference Proceedings, 2019, , .	0.3	1
22	A review of numerical models for masonry structures. , 2019, , 3-53.		20
23	Seismic assessment of historical masonry structures through advanced nonlinear dynamic simulations: applications to castles, churches, and palaces. , 2019, , 163-200.		4
24	Comparative fragility methods for seismic assessment of masonry buildings located in Muccia (Italy). Journal of Building Engineering, 2019, 25, 100813.	1.6	63
25	Seismic Assessment of a 14th-Century Stone Arch Bridge: Role of Soil–Structure Interaction. Journal of Bridge Engineering, 2019, 24, .	1.4	17
26	Earthquake-induced damage assessment and partial failure mechanisms of an Italian Medieval castle. Engineering Failure Analysis, 2019, 99, 292-309.	1.8	55
27	Base seismic isolation of a historical masonry church using fiber reinforced elastomeric isolators. Soil Dynamics and Earthquake Engineering, 2019, 120, 127-145.	1.9	43
28	Seismic assessment of interacting structural units in complex historic masonry constructions by nonlinear static analyses. Computers and Structures, 2019, 213, 51-71.	2.4	63
29	An Interdisciplinary Approach for the Seismic Vulnerability Assessment of Historic Masonry Buildings: The Case Study of the Ex Jesuits College in Amantea (Italy). RILEM Bookseries, 2019, , 1247-1256.	0.2	1
30	Nonlinear Structural Performance of a Historical Brick Masonry Inverted Dome. International Journal of Architectural Heritage, 2020, 14, 1161-1179.	1.7	11
31	Finite element modelling of a historic church structure in the context of a masonry damage analysis. Engineering Failure Analysis, 2020, 107, 104233.	1.8	29
32	Structural investigation of Mnajdra megalithic monument in Malta. Journal of Cultural Heritage, 2020, 41, 96-105.	1.5	9
33	Modeling Strategies for the Computational Analysis of Unreinforced Masonry Structures: Review and Classification. Archives of Computational Methods in Engineering, 2020, 27, 1153-1185.	6.0	245
34	The seismic sequence of 2016–2017 in Central Italy: a numerical insight on the survival of the Civic Tower in Amatrice. Bulletin of Earthquake Engineering, 2020, 18, 1371-1400.	2.3	8
35	Effect of soil properties on the seismic damage assessment of historical masonry minaret–soil interaction systems. Structural Design of Tall and Special Buildings, 2020, 29, e1694.	0.9	20
36	Seismic vulnerability of masonry buildings: Numerical insight on damage causes for residential buildings by the 2016 central Italy seismic sequence and evaluation of strengthening techniques. Journal of Building Engineering, 2020, 28, 101081.	1.6	17

CITATION REPORT

#	ARTICLE	IF	CITATIONS
37	Influences of earthquake input models on nonlinear seismic performances of minaret-foundation-soil interaction systems. Soil Dynamics and Earthquake Engineering, 2020, 139, 106368.	1.9	13
38	Failure analysis of a Portuguese cultural heritage masterpiece: Bonet building in Sintra. Engineering Failure Analysis, 2020, 115, 104636.	1.8	27
39	Seismic vulnerability assessment methodology for historic masonry buildings in the near-field areas. Engineering Failure Analysis, 2020, 115, 104662.	1.8	40
40	Seismic sequence of 2016–17: Linear and non-linear interpretation models for evolution of damage in San Francesco church, Amatrice. Engineering Structures, 2020, 211, 110418.	2.6	13
41	Rapid post-earthquake damage localization and quantification in masonry structures through multidimensional non-linear seismic IDA. Engineering Structures, 2020, 219, 110841.	2.6	41
42	Seismic behaviour of self-insulating inner-framed bearing walls with openings. Canadian Journal of Civil Engineering, 2021, 48, 897-911.	0.7	1
43	A micro-modeling approach for the prediction of TRM bond performance on curved masonry substrates. Composite Structures, 2021, 256, 113065.	3.1	7
44	Nonlinear soil deformability effects on the seismic damage mechanisms of brick and stone masonry arch bridges. International Journal of Damage Mechanics, 2021, 30, 431-452.	2.4	14
45	A cost-effective FRCM technique for seismic strengthening of minarets. Engineering Structures, 2021, 229, 111672.	2.6	11
46	Overview on the Nonlinear Static Procedures and Performance-Based Approach on Modern Unreinforced Masonry Buildings with Structural Irregularity. Buildings, 2021, 11, 147.	1.4	16
47	Ambient vibration testing and empirical relation for natural period of historical mosques. Case study of eight mosques in Kermanshah, Iran. Construction and Building Materials, 2021, 289, 123191.	3.2	16
48	Numerical analysis of historical masonry domes: A study of St. Peter's Basilica dome. Structures, 2021, 31, 80-86.	1.7	12
49	Reduction of earthquake risk of the National Palace of Sintra in Portugal: The palatine chapel. International Journal of Disaster Risk Reduction, 2021, 60, 102172.	1.8	5
50	Numerical insight on the interaction effects of a confined masonry tower. Engineering Structures, 2021, 237, 112195.	2.6	6
51	Unpacking seismic risk in Italian historic centres: A critical overview for disaster risk reduction. International Journal of Disaster Risk Reduction, 2021, 59, 102260.	1.8	6
52	Behavior of precast composite columns under axial and transverse forces. Journal of Building Engineering, 2021, 44, 103262.	1.6	1
53	The 2016 Central Italy seismic sequence: linear and non-linear interpretation models for damage evolution in S. Agostino's church in Amatrice. Bulletin of Earthquake Engineering, 2021, 19, 1467-1507.	2.3	5
54	Low Cost Frictional Seismic Base-Isolation of Residential New Masonry Buildings in Developing Countries: A Small Masonry House Case Study. Open Civil Engineering Journal, 2017, 11, 1026-1035.	0.4	13

CITATION REPORT

ARTICLE IF CITATIONS # Historic City Centers After Destructive Seismic Events, The Case of Finale Emilia During the 2012 Emilia-Romágna Earthquake: Advanced Numerical Modelling on Four Case Studies. Open Civil Engineering Journal, 2017, 11, 1059-1078. 55 0.4 7 Cultural Heritage and Earthquake: The Case Study of "Santa Maria Della Carit̉ۥin Ascoli Piceno. Open Civil Engineering Journal, 2017, 11, 1079-1105. 0.4 44 Evaluation of the Structural Balance of Large Scale Historical Castle and City Walls Under 57 0.4 2 Environmental Effects By Analytical Methods. Journal of Polytechnic, 2022, 25, 545-555. Seismic behavior and damage assessment of two historical fortified masonry palaces with corner 1.8 towers. Engineering Failure Analysis, 2022, 134, 106003. Seismic Assessment of Historical Masonry Buildings at Different Scale Levels: A Review. Applied 59 1.33 Sciences (Switzerland), 2023, 13, 1941. Seismic Assessment of the Archangeloi (Başmelekler) Church in Kumyaka, Türkiye. Buildings, 2023, 13, 787. 1.4 Finite element modelling of FRP-reinforced triplets subjected to shear tests. AIP Conference 66 0.3 0 Proceedings, 2023, , . Evaluation of Damage Caused by Soil Settlements in a Historical Masonry Building. Sustainable Civil Infrastructures, 2023, , 15-27.

**CITATION REPORT**